## Some Solder Specialist

Kirti Hirani

Print Name

## **Landlord Gas Safety Record**

Cert. No. 8616

Safety Inspection and reporting carried out in accordance with the Gas Safety (Installation and Use) Regulations 1998 section 26(9) and the Gas Industry Unsafe Situations Procedure.

Company / Installer							Job Address							Customer / Landlord							
En	gineer	Kirti Hirani					ame					N.	ame	The Landlord							
Company Address Post Code Tel No. Gas Safe Reg ID Card No.		National Boiler Specialist					dress 3					C	Company	C/O Oyster Properties.							
		18 The Broadway Eastlane					Kenton Avenue					A	Address								
							Н	Harrow							845 Honeypot Lane						
		Wembley					G	Greater London							Stanmore						
		Middlesex HA9 8JU 07599911188 586712 4392124				Post Code Tel. No	H	HA1 2BN							United Kingdom						
														ost Code	HA7 1AR						
													Te	Tel. No	020 8951 5558						
Αp	pliance De	etails						Inspec	tion Details												
- -	Location		Appliance Type	Make	Mode	el	Flue Type	e Landlord's Appliance Inspected		Operating Pressure	Heat Input (kW/h)	High Comb		Low Combustion	on Safety device(	s) Ventilation	Visual condition	Flue	Appliance	Appliance safe	
								Appliance		(mbar)				Reading  Reading  Reading		Provision satisfactory	of flue and termination satisfactory	Performance test	Serviced	to use	
1	Outer Sto	ore	Central Heating Boiler	Baxi	830 H	eat	RS	Yes	Yes	NA	29.4	0.0002 1	5 8.6	5 NA NA N	IA Yes	Yes	Yes	Pass	Yes	Yes	
2																					
3																					
4																					
5																					
6																					
Defects / Identified							Labels and Warning Notice Issued					d C	:O Alarm(s	5)		Option	al Check	S			
	1										NA			CO Alarm(s) f	itted	Yes	Smoke	Alarm(s) fit	ted	Yes	
	2										IVA		- 11								
3														CO Alarm(s) tested		Smoke Alarm(s) tested					
4													_     6	and Satisfactory			and Sat	and Satisfactory			
5																		Water quality/level of inhibitor			
	U															acceptable					
En	nergency Cor	ntrol Ad	ccessible Yes Gas	Tightness Satisfactory Ye	S	Comr	nents														
Gas Installation Pipework Visual Inspection Satisfactory Yes						Smo	Smoke alarm on a fire panel														
	Equipotenti	al Bond	ding No																		
NE	XT INSPEC	TION E	DUE BEFORE	03-Mar-2026																	
Sic	natures																				
Iss	ued by:	Signe	ed Alia	_		Received S	Signed							Date	25-J	an-2025					
			1 \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		L	y:															

Print Name