Landlord Home Owner Gas Safety Record



This inspection is for gas safety purposes only to comply with the Gas Safety (Installation and Use) Regulations. Flues have been inspected and checked for satisfactory evacuation of products of combustion. A detailed internal inspection of the flue integrity, construction and the lining has NOT been carried out.

Registered business J				Job address			Land	Landlord/agent			Certificate information			
Gas safe ID 601928 Plumbco Heating Ltd 220 Kingsway				Flat 7 Oakfield Mansions 6-10 Oakfield Grove Bristol BS8 2BN			7 Wo Redl Brist BS6	Ms Lucy Berthoud 7 Woodstock Avenue Redland Bristol BS6 6EW +44 07913508659			Date 04/04/2025 Number 4912 Next inspection due 04/04/2026			
No	Location Appliance type		Make/model		Flue type	Landlor applian		Appliance nsp?	Combustion analyser reading	Operating pressu or heat input	re Safety device correct oper	ce(s) ration		
1	Kitchen	tchen Hob		Bosch/4 Burner			Yes		⁄es		20.5mbar	Yes		
2	Utility Combination boil		tion boiler	Worcester Bosch/28 CI		OI Compact		Yes		′es	51	18mbar	Yes	
No	Ventilation provision satisfactory			ual condition of the flue & nination satisfactory		Flue performance checks		Appliance serviced		pliance fe to use	Approved CO alarm fitted?	Is CO alarm in date?	Testing of CO a satisfactory	larm
1	Yes		N/A			N/A	N/A		Yes	S	N/A N/A N/A		N/A	
2	Yes		Yes		Pass		N/A		Yes	S	Yes	Yes	Yes	
No	Defect(s) identified			Remedial action taken Warn				Warning/Advice notice issued		Number of appliances tested 2				
										Gas installation pipework (visual inspection) satisfactory?			Yes	
									Gas tightness test			•		
												ntrol valve accessible? Yes		
													Yes	
										Audible carbon monoxide alarm fitted?				
Engineer information Received by information Comments								and and Man	la la la					
Engineer name: Jed Ferris Gas safe card ID: 5774462 Signature:				Name: Received by: No person present Signature:				perforn the gas	The right hand hinge was broken and it has been replaced Was not able to perform a tightness test of the whole installed as there was no access to the gas meter, a tightness test was performed from the gas isolation point as it enters the property					

Analyser readings	App 1	App 2	App 3	App 4
Working pressure (at meter)		mbar		
Working appliance pressure		18 mbar		
Co parts per million		51		
Percentage co2		10.5		
Percentage oxygen		4.9		
Co/Co2 ratio		0.0005		
Gross flue gas temperature		53		
Gas rate (if applicable)				